



Figure 1-6

Configuration of overflow weir modification and position of fish release hose at spillbay 6 at The Dalles Dam. The release hose was positioned approximately 6 ft below the surface and just upstream of the weir (Steve Dingman, ACOE, The Dalles Dam, pers. comm.).